

920-138 braindumps

Nortel NCSS

920-138: NNCSS Succession 1000/1000M Ris.3.0 Exam

Practice Exam: 920-138 Exams

Exam Number/Code: 920-138

Exam Name: NNCSS Succession 1000/1000M Ris.3.0 Exam

Questions and Answers: 59 Q&As

([NCSS](#))



Exam : [920-138](#)

"NNCSS Succession 1000/1000M Ris.3.0 Exam", also known as 920-138 exam, is a Nortel certification. With the complete collection of exam questions, Just4Study has assembled to take you through 59 Q&As to your 920-138 exam preparation. In the 920-138 exam resources, you will cover every field and category in Nortel Certification helping to ready you for your successful Nortel Certification.

The exam questions cover the latest real test and with all the correct answer. we promise the Q&A for Nortel NCSS 920-138 (NNCSS Succession 1000/1000M Ris.3.0 Exam) examination of original title complete coverage. 920-138 exam questions help you pass the exam.

Just4Study 920-138 Feature:

* High quality - High quality and valued for the 920-138 Exam: 100% Guarantee to Pass Your 920-138 exam and get your NCSS certification.

* Authoritative - Authoritative braindumps with complete details about 920-138 exam.

* Cheaper - Our Just4Study products are cheaper than any other website. With our completed NCSS resources, you will minimize your **Nortel NCSS** cost and be ready to pass your 920-138 exam on Your First Try, 100% Money Back Guarantee included!

* Free - Try free NCSS demo before you decide to buy it in <http://www.Just4Study.com>.

Just4Study Guarantee:

Just4Study provides the most competitive quality of all exams for the customers, we guarantee your success at the first attempt with only our Certification Question&Answers, if you do not pass the 920-138 exam at the first time, we will not only arrange FULL REFUND for you, but also provide you another exam of your claim, ABSOLUTELY FREE!

Free 920-138 Demo Download

Just4Study offers free demo for NCSS 920-138 exam (NNCSS Succession 1000/1000M Ris.3.0 Exam). You can check out the interface, question quality and usability of our practice exams before you decide to buy it. We are the only one site can offer demo for almost all products.

The Questions & Answers cover the latest real test and with all the correct answer.we promise the Q&A for **Nortel NCSS 920-138** examination of original title complete coverage.920-138 Questions & Answers help you pass the exam. Otherwise,we will give you a full refund.

VUE/Prometric Code: 920-138

Exam Name: NNCSS Succession 1000/1000M Ris.3.0 Exam(NCSS)

Questions and Answers: 59 Q&A

[Nortel 920-138](#) Test belongs to one of the NCSS certified test, if needs to obtain the NCSS certificate, you also need to participate in other related test, the details you may visit the [NCSS](#) certified topic, in there, you will see all related NCSS certified subject of examination.

Just4Study professional provide NCSS 920-138 the newest Q&A, completely covers 920-138 test original topic. With our complete NCSS resources, you will minimize your NCSS cost and be ready to pass your 920-138 tests on Your First Try, 100% Money Back Guarantee included!

Just4Study Help You Pass Any IT Exam

[Just4Study.com](#) offers incredible career enhancing opportunities. We are a team of IT professionals that focus on providing our customers with the most up to date material for any IT certification exam. This material is so effective that we Guarantee you will pass the exam or your money back.

Exam : NORTEL 920-138

Title : NNCSS Succession 1000/1000M Ris.3.0 Exam

1. Click the exhibit button. A customer has a Succession 1000/1000M Rls. 3.0 system. The system outputs a FIJI0006 message and the customer reports that many Internet Telephones are out-of-service. Which action should you take to resolve the issue?

- A. Initialize or Sysload the system to clear FIJI card corruption.
- B. Reset the card and check the interface cable connections on the faceplate.
- C. Check the status of the network card in Overlay LD 32 using the STAT NWK 6 command. Then enter the ENLG 6 command to return the network group to service.
- D. Check the ring status in Overlay LD 39 using the STAT RING 0 or 1 command. Then enter the RSET and RSTR commands to reset counters and restore ring to service.

Answer: D

2. A customer has just completed upgrading their existing Succession Communication Server for Enterprise (CSE) 1000 Rls. 2.0 system to a Succession 1000 Rls 3.0 system. However, they are now unable to complete calls from their Internet Telephones using pathways that route through the Media Gateway. The system consists of the following components: ? two digital trunk cards ? one Voice Gateway Media Card (VGMC) running IP Line 3.1 ? one analog trunk card ? one Signaling Server Assume that the Succession System Controller (SSC) is running fine and all cable connections are correct. What is a solution for this customer?

- A. Replace the VGMC as it is most likely defective.
- B. Try a different combination of Internet Telephones.
- C. Change the Class of Service (CLS) to enable completion of Media Gateway calls.
- D. Ensure that the VGMC's Digital Signal Processors (DSPs) are registered with the Call Server.

Answer: D

3. Given the following information: ? A company has a Succession 1000/1000M Rls. 3.0 system providing IP-PBX services. ? While running maintenance via a serial connection on one of the Voice Gateway Media Cards (VGMCs), a technician discovers that the display from the VGMC is slow and does NOT respond to the keyboard. ? Assume that a faulty card is NOT the cause of VGMC issue. What is the mostly likely cause of the VGMC issue and the required corrective action?

- A. The terminal is set to the wrong baud rate. Set the baud rate to 9,600, and then restart the session.
- B. The terminal is set to the wrong baud rate. Set the baud rate to 19,200, and then restart the session.
- C. The terminal's hardware flow control is enabled. Set the hardware flow to none , and then close and restart the session.
- D. The terminal's flow control is set to none . Set the flow control to hardware , and then close and restart the session.

Answer: C

4. You are installing a small Succession 1000/1000M RIs. 3.0 system with four Media Gateways. Although the Media Gateways come up normally and appear to work properly when tested, one of the Media Gateway's link LEDs on the front of the Call Server's Succession System Controller (SSC) did NOT light up. Which task should you perform first?
- A. Replace the IP daughterboard on the Call Server's SSC card.
 - B. Check the interface from the back of the Call Server to the LAN interface for power.
 - C. Replace the IP daughterboard on the associated Media Gateway's SSC card.
 - D. Verify that all of the connectors between the IP daughterboard and the Call Server's SSC card are in place.

Answer: D

5. Given the following information: ? A company has a Succession 1000/1000M RIs. 0 system providing IP-PBX services at their headquarters. ? A sister office has a Meridian 1 Internet Enabled (IE) Option 11C RIs. 25.40 that is connected to the Succession system with Primary Rate Interface (PRI) TIE lines. ? Calls can be placed and received between the two offices. ? The CallPilot 2.0 system at the headquarters is being used as the voice mail system for both offices using a Network Messaging System (NMS). ? The message waiting lights at the sister office do NOT light when a message is left in the corresponding CallPilot mailbox. ? The message waiting lights at the headquarters are working as designed. What should you check in the Succession system database at both offices to resolve this message waiting light malfunction? (Choose two.)

- A. Check to see that the Multimedia Allowed (MMA) option is listed in the Class of Service (CLS) of the Automatic Call Distribution (ACD) agents using CallPilot.
- B. Check to see that the Private Network Identifier (PNI) defined in the Customer Data Block (CDB) of the headquarters matches the PNI defined in the Route Data Block (RDB) of the TIE lines at the sister office.
- C. Check to see that the PNI defined in the CDB of the sister office matches the PNI defined in the RDB of the TIE lines at the headquarters.
- D. Check to see that Message Waiting Allowed (MWA) is defined in the CLS of each of the connecting TIE trunks defined in Overlay LD 14 at the headquarters.
- E. Check to see that MWA is defined in the CLS of each of the connecting TIE trunks defined in Overlay LD 14 at the sister office.

Answer: BC

6. A customer has a Succession 1000/1000M RIs 3.0 system. Give the following information: ? Two IP Telephony nodes have been configured. ? One IP Telephony node consists of a Signaling Server. ? The second IP Telephony node consists of two Voice Gateway Media Cards (VGMCs). ? The Signaling Server and the two VGMCs are located on separate Telephony LAN (TLAN) subnets. An Internet Telephone registered with the Signaling Server calls a digital telephone. Next the digital telephone rings and the Internet Telephone user hears ringback. After the call has been answered, both users experience a NO speech path condition in either direction. What is the most likely cause of this condition?

- A. The Internet Telephone could NOT access a VGMC channel in its own IP Telephony node.
- B. The Internet Telephone does NOT have an IP route to the TLAN subnet of the IP Telephony node that contains the VGMC, and the VGMC does NOT have an IP route to the Internet Telephone.
- C. The VGMC Terminal Numbers (TNs) are assigned to a different customer number than the digital telephones.
- D. The Internet Telephone does NOT have an IP route to the Embedded LAN (ELAN) subnet of the IP Telephony node that contains the VGMC, and the VGMC does NOT have an IP route to the Internet Telephone.

Answer: B

7. A customer with a Succession 1000/1000M RIs. 3.0 system reports that their i200x Internet Telephones frequently reboot. How do you review the logs within the IP Telephony leader device to see if there are any reported reason codes? (Choose two.)

- A. Login to the Call Server and in Overlay LD 2 review traffic report 16.
- B. Login to the Call Server and in Overlay LD 117 review traffic report 16.
- C. Use Element Management (EM) to review Syslogs. (EM click System Status > IP Telephony > expand the IP Telephony node and click SYSLOG for the leader device.)
- D. Use the Optivity Telephony Manager (OTM) 2.1 Internet Telephones application to review Syslogs. (Highlight the IP Telephony node and the leader device > click Configuration > Card > Properties > click Maintenance tab

> click Open Log file for Syslogs.)

Answer: CD

8. A customer with a Succession 1000/1000M RIs. 3.0 system has concerns about voice quality when using their i200x Internet Telephones. How can you review the Operational Measurement (OM) reports to verify if the i200x Internet Telephones are experiencing excessive packet loss or jitter? (Choose two.)

- A. Review traffic data report 16 that reports on the system's zone bandwidth usage.
- B. Use the Optivity Telephony Manager (OTM) 2.1 Internet Telephones application to review OM reports (File & Report & Generate).
- C. Use Element Management (EM) to review the OM reports (EM Click System Status & IP Telephony & Expand Node & Select OM Report).
- D. Use the OTM 2.1 Internet Telephones application to review bandwidth usage statistics (File & Report & Bandwidth Usage).
- E. Use EM to review bandwidth usage statistics (EM Click System Status & IP Telephony & Logs & Bandwidth Usage Log).

Answer: BC

9. Given the following information: ? A company has a Succession 1000/1000M RIs. 3.0 system providing IP-PBX services. ? The system was recently upgraded from Release 1.1 to Release 3.0 successfully. ? The system is using two Voice Gateway Media Cards (VGMCs). ? The passwords for the VGMCs were CARD1 and CARD2 respectively. ? When the Succession administrator attempts to log in to the VGMCs to check the maintenance display, an error message is received stating that the passwords are invalid. ? Assume that a faulty card is NOT the cause of the error message. What does the error message communicate about the state of the VGMCs?

- A. All VGMCs must be re-established in the system.
- B. All VGMCs revert to the default password.
- C. All VGMCs passwords are disabled and require reactivation.
- D. All VGMCs revert to the PWD1 programmed in Overlay LD 17 when downloaded.

Answer: D

10. A company has a Succession 1000/1000M RIs. 3.0 system providing IP-PBX services. When the Succession administrator tries to log in to the Succession server using Element Management (EM), the error code WEB4008 is received. This error code indicates that ? LVUHFHLYHG7KLVHUURUFRGHLQGLFDWHVWVKDW NO idle Teletype (TTY) is available.?What should you check in the system configuration to resolve this error?

- A. Verify that the assigned TTY has service changes (SCH) listed.
- B. Verify that at least two Pseudo TTYs (PTYs) are configured on the Succession server.
- C. Verify that the Embedded LAN (ELAN) is configured properly on the Succession server.
- D. Verify that NO other administrators are accessing the Succession system via the serial maintenance port that does NOT take up a PTY.

Answer: B

[920-138 Braindumps](#)

Related 920-138 Exams

[920-803](#) Nortel technology standards and protocol for ip telephony solutions

[922-097](#) Comm.Server 1000 Upgrades to RIs.5.0 for Technicians

[920-250](#) nncss-passport 8600

[920-322](#) nncss succession 1000/1000m rls 3.0 db for technicians

[922-093](#) Communication Server 1000 RIs.5.0 System Admin & Mgmt

[922-096](#) Comm.Server 1000 RIs.5.0 Branch Office Install & Comm.

[922-095](#) Communication Server 1000E RIs.5.0 Install & Commissioning

[920-215](#) nncss-passport 7000/15000 exam

920-331 *Mommunication Server 1000 Ris.5.0 Database Administrator*

920-326 *nncds-symposium contact center poftfolio*

920-138 *NNCSS Succession 1000/1000M Ris.3.0 Exam*

920-251 *nncss-alteon*

920-133 *NNCSS Baystack Switching*

920-501 *nncss-optera metro 5000*

920-170 *symposium call center server 5.0 applicaiont developer*

920-460 *ncse wireless lan*

920-249 *Nortel Application Switch Ris.23XConfig &Admin*

920-330 *Mommunication Server 1000 Ris.5.0 IP Networking Design*

920-245 *Ethernet Switching*

920-172 *NCSS-Nortel Communication Control Toolkit Ris.6.0*

Other Nortel Exams

920-326 920-316 920-130 922-071 920-246 920-020 920-238 920-165

920-327 920-569 922-104 920-471 920-352 920-806 920-807 920-191

920-442 920-180 922-098 920-118