

000-078 braindumps IBM IBM certifications I

000-078: eServer BladeCenter

Practice Exam: 000-078 Exams

Exam Number/Code: 000-078

Exam Name: eServer BladeCenter

Questions and Answers: 148 Q&As

([IBM certifications I](#))



"eServer BladeCenter", also known as 000-078 exam, is a IBM certification.

Exam : [000-078](#)

With the complete collection of exam questions, Just4Study has assembled to take you through 148 Q&As to your 000-078 exam preparation. In the 000-078 exam resources, you will cover every field and category in IBM Certification helping to ready you for your successful IBM Certification.

The exam questions cover the latest real test and with all the correct answer. we promise the Q&A for IBM IBM certifications I 000-078 (eServer BladeCenter) examination of original title complete coverage. 000-078 exam questions help you pass the exam.

Just4Study 000-078 Feature:

* High quality - High quality and valued for the 000-078 Exam: 100% Guarantee to Pass Your 000-078 exam and get your IBM certifications I certification.

* Authoritative - Authoritative braindumps with complete details about 000-078 exam.

* Cheaper - Our Just4Study products are cheaper than any other website. With our completed IBM certifications I resources, you will minimize your **IBM IBM certifications I** cost and be ready to pass your 000-078 exam on Your First Try, 100% Money Back Guarantee included!

* Free - Try free IBM certifications I demo before you decide to buy it in <http://www.Just4Study.com>.

Just4Study Guarantee:

Just4Study provides the most competitive quality of all exams for the customers, we guarantee your success at the first attempt with only our Certification Question&Answers, if you do not pass the 000-078 exam at the first time, we will not only arrange FULL REFUND for you, but also provide you another exam of your claim, ABSOLUTELY FREE!

Free 000-078 Demo Download

Just4Study offers free demo for IBM certifications I 000-078 exam (eServer BladeCenter). You can check out the interface, question quality and usability of our practice exams before you decide to buy it. We are the only one site can offer demo for almost all products.

The Questions & Answers cover the latest real test and with all the correct answer.we promise the Q&A for **IBM IBM certifications I 000-078** examination of original title complete coverage.000-078 Questions & Answers help you pass the exam. Otherwise,we will give you a full refund.

VUE/Prometric Code: 000-078

Exam Name: eServer BladeCenter(IBM certifications I)

Questions and Answers: 148 Q&A

[IBM 000-078](#) Test belongs to one of the IBM certifications I certified test, if needs to obtain the IBM certifications I

certificate, you also need to participate in other related test, the details you may visit the [IBM certifications](#) | certified topic, in there, you will see all related IBM certifications | certified subject of examination.

Just4Study professional provide IBM certifications | 000-078 the newest Q&A, completely covers 000-078 test original topic. With our complete IBM certifications | resources, you will minimize your IBM certifications | cost and be ready to pass your 000-078 tests on Your First Try, 100% Money Back Guarantee included!

Just4Study Help You Pass Any IT Exam

Just4Study.com offers incredible career enhancing opportunities. We are a team of IT professionals that focus on providing our customers with the most up to date material for any IT certification exam. This material is so effective that we Guarantee you will pass the exam or your money back.

Exam : IBM 000-078

Title : eServer BladeCenter

1. An administrator is creating a Microsoft Windows Native Install image with IBM Remote Deployment Manager (RDM) 4.20. During the creation of the image, the task fails. What is the most likely cause of the failure?

- A. The computer name is invalid.
- B. The Windows product ID is incorrect.
- C. The size of the image has exceeded 2GB.
- D. The source files are not on the RDM server.

Answer: C

2. Which of the following can be used to update firmware on all Ethernet switch module options?

- A. FTP
- B. TFTP
- C. Web Browser
- D. Management Module

Answer: B

3. A customer has a BladeCenter with eight HS20 blades, two Nortel L2/L3 Ethernet switches, and no redundant KVM/Management Module. There are three VLANs set up in the chassis. The customer cannot ping from an external workstation to the blades. Which of the following is most likely the cause of the problem?

- A. The Nortel L4-7 upgrade was not installed.
- B. The Management Module internal interface is disabled.
- C. Firmware should have been updated on each of the Nortel switches.
- D. Tagging is not enabled for all ports on the switch modules and the external switches.

Answer: D

4. A customer has a small 100Mb LAN network and wants to add five servers to their network in a new BladeCenter chassis. The customer has small application servers, each with their own internal hard drives. Each server requires access to two different LAN segments. The customer is considering installing a SAN; however that will be a future project. Which of the following would best satisfy the customer's requirements?

- A. Two Optical Pass-thru Modules
- B. Two BladeCenter 4-port Gigabit Ethernet Switch Modules
- C. Two Copper Pass-thru Modules, two Optical Pass-thru Modules
- D. Two Optical Pass-thru Modules, Fibre Channel Switch Modules

Answer: B

5. A customer wants a new BladeCenter chassis installed with redundant power sources. What is the minimum PDU configuration, recommended by IBM, to support a single chassis fully populated with 2000W power supplies?

- A. 2 Rack PDUs - 100-127Vac, 15a

- B. 1 Front End PDU - 208Vac, 30a, single-phase
- C. 2 Front End PDUs - 208Vac, 30a, single-phase
- D. 2 Enterprise PDUs - 208Vac, 60a, single-phase

Answer: C

6. Which TWO of the following hardware alerts can be sent to each blade server's IBM Director agent?

- A. Fan Alert
- B. Virus Alert
- C. Voltage alert
- D. Intruder Alert
- E. Temperature alert
- F. Power Supply failure

Answer: CE

7. A customer needs a BladeCenter solution that will host VMware ESX version 2.5 servers. The BladeCenter will be populated with HS20 blades with the appropriate I/O adapter, sufficient power modules and two Ethernet modules. They will also be implementing Virtual Center and VMotion. Which of the following BladeCenter options is required to complete the solution?

- A. Copper Pass-thru Module
- B. TopSpin Switch Module
- C. Cisco Switch Module
- D. Fibre Switch Module

Answer: D

8. A customer wants to set up a 512 node (HPC Cluster) BladeCenter environment for an extremely high bandwidth application. Which of the following is the most appropriate switch module to interconnect the multiple chassis needed?

- A. Topspin Infiniband Switch Module
- B. BladeCenter Copper Pass-thru Module
- C. BladeCenter Optical Pass-thru Module
- D. Nortel Networks Layer 2-7 GbE Switch Module

Answer: A

9. A customer plans to deploy an IBM BladeCenter Chassis. It will contain:

Two Nortel Networks Layer 2-7 GB Ethernet Switch Modules

Two Brocade Enterprise Fibre Channel Switch Modules

Redundant Management Modules

How many copper RJ45 and fibre ports are on the back of the chassis?

- A. 8 copper RJ45 ports and 4 fibre channel ports
- B. 8 copper RJ45 ports and 12 fibre channel ports
- C. 10 copper RJ45 ports and 4 fibre channel ports
- D. 10 copper RJ45 ports and 12 fibre channel ports

Answer: C

10. Microsoft Windows Server 2003 is installed on several blades configured with static IP addresses, gateway and DNS information. None of the blades are able to ping the gateway or other servers in the same subnet within the chassis. The "Show icon in notification area when connected" box in the Network property shows connection to the network. Which of the following will resolve the problem?

- A. Correct the DNS address.
- B. Correct the subnet mask.
- C. Correct the gateway address.
- D. Connect the network cable to the router.

Answer: B

11. After a completed installation of Microsoft Windows Server 2003 Standard Edition on an HS20 8843 blade server, there is no network connectivity. Which of the following should be done to resolve this problem?

- A. Apply Windows 2003 Service Pack 1.
- B. Install the Broadcom network driver.
- C. Enable the Network adapter from the Management Module Web Interface.
- D. Change Ethernet adapters duplex mode to auto within network settings.

Answer: B

12. A customer is replacing several existing servers and is consolidating them into a BladeCenter solution. The following servers are being considered for consolidation:

Two Microsoft SQL server two-node clusters, with each node containing four processors and hot swap SCSI drives

Two Physical Microsoft Active Directory Servers

22 Physical Citrix servers ? Three Physical Web servers

One Physical Virtual Center and VMotion server

Eight Physical VMware ESX servers

Which of the following configurations will best satisfy the requirements?

- A. Three BladeCenter Chassis, two Fibre modules, eight Ethernet Modules
- B. Three BladeCenter Chassis, four Fibre modules, eight Ethernet Modules
- C. Four BladeCenter Chassis, two Fibre modules, four Ethernet Modules
- D. Four BladeCenter Chassis, four Fibre modules, eight Ethernet Modules

Answer: D

13. A customer requires 10/100/1000 Ethernet Switch Modules for a BladeCenter chassis. For the future, they would like to explore the capability of upgrading to layers 4-7. Which of the following modules will allow them to perform a field upgrade to layers 4-7?

- A. Nortel Networks Layer 2-7 GB Ethernet Switch Module
- B. IBM BladeCenter 4-port Gigabit Ethernet Switch Module
- C. Nortel Networks L2/3 Copper GbE Switch Module for IBM eServer BladeCenter
- D. IBM BladeCenter 4-port Cisco Systems Intelligent Gigabit Ethernet Switch Module

Answer: C

14. A customer would like to add five HS20 8843 blades into an existing BladeCenter Chassis with two HS20 8832 and 1800W power supplies. Which of the following is the most cost-efficient solution without introducing any downtime?

- A. Add a 2000w power supply kit and place the new Blades in slots 7 through 11
- B. Add additional 1800w power supplies and put the five HS20 8843 into slots 7 through 11
- C. Replace the 1800w with 2000w power supplies and place the new blades in slots 3 through 7
- D. Replace the 1800w power supplies with 2000w power supplies and add an additional 2000w power supply kit

Answer: A

15. What is the default network address of the Management Module and any modules placed in an I/O module bay?

- A. 192.0.0.x
- B. 192.16.70.x
- C. 192.168.0.x
- D. 192.168.70.x

Answer: D

16. What is an important benefit of using a switch compliant to IEEE 802.1Q?

- A. The switch allows multiple proprietary protocols to forward traffic between switches.
- B. The switch allows use of logical groups within a switch in order to control broadcast traffic.
- C. The switch can combine physical links into one point-to-point logical link for increased bandwidth.
- D. The switch discovers a loop-free network (tree) and provides a single physical path between any two stations.

Answer: B

17. After installing a new BladeCenter, IBM Director has successfully discovered the new chassis. Which of the following tasks must first be performed before launching the Deployment Wizard in IBM Director?

- A. Update the BladeCenter Management Module firmware
- B. Enable the Ethernet switch ports for external management
- C. Select "Request Access" to the Management Module
- D. Move the Management Module Ethernet port to a management VLAN

Answer: C

18. A customer requires six HS20 blade servers in a new BladeCenter Chassis. Each blade requires redundant paths to two separate network segments. Which hardware is necessary to meet these requirements?

- A. Four Copper Pass-thru Modules
- B. Four Gigabit Ethernet Switches Modules
- C. Two Copper Pass-thru Modules and a Gigabit Ethernet Daughter Card in each blade
- D. Four Gigabit Ethernet Switch Modules and a Gigabit Ethernet Daughter Card in each blade

Answer: D

19. A customer has a BladeCenter with three HS20 blades that will be accessing one network segment and a mix of three HS20 blades and two HS40 blades that will be accessing a different LAN segment. What is the minimum number of switch modules and VLAN IDs required?

- A. One Ethernet switch module and two VLAN IDs
- B. Two Ethernet switch modules and no VLAN IDs
- C. Two Ethernet switch modules and two VLAN IDs
- D. One Ethernet switch module and eight VLAN IDs

Answer: A

20. An administrator has created a customized Linux Native Install operating system image to deploy to the blades. When the administrator creates a task that uses this image, the installation fails. Which of the following is the most likely cause?

- A. boot.ini is incorrectly configured
- B. All packages and package groups had been selected
- C. Only the required packages and package groups were installed
- D. The packages and package groups present in the modified comps file were not selected

Answer: D

[000-078 Braindumps](#)

Related 000-078 Exams

[000-223](#) *IBM System p Administrator*

[000-377](#) *Test 000-377, IBM WebSphere Application Server Network Deployment V7.0, Core Administration*

[000-974](#) *Power Systems Technical Support for i*

[000-417](#) *IBM WebSphere Information Analyzer v8.0*

[000-015](#) *IBM Maximo Asset Management V7.1 Implementation*

[000-913](#) *informix 4gl development*

[000-316](#) *IBM WebSphere Integration Developer V6.1*

[000-431](#) *IBM Tivoli Storage Manager V5.5 Administration*

[000-667](#) *IBM Test 667, Architectural Design of SOA Solutions*

[000-665](#) *Architecture design of soa solution*

[000-908](#) *Tivoli Monitoring V6.2 Implementation*

000-669 SOA Fundamentals (2008)

000-111 IBM Distributed Systems Storage Solutions Version 7

000-872 ib m tivoli storage manager v5.2 implementation

000-011 IBM Tivoli AP Dependency+Discovery Mgr V7.1 Implementation

000-286 test286,application development wwebsphere studio,v5.0

000-995 IBM Web Sphere Process Server V6.1.System Administration

000-890 IBM Tivoli Monitoring V6.1 Implementation

000-076 IBM System x Sales

000-017 Foundations of Tivoli process automation engine V7.1

Other IBM Exams

000-J02 000-111 000-897 000-112 000-P01 000-142 000-341 COG-132

000-289 000-512 000-086 000-442 000-773 000-M23 000-377 000-774

000-438 LOT-980 000-010 000-733