

## 920-332 braindumps

### Nortel NCSS

#### 920-332: Mommunication Server 1000 Ris.5.0 Install & Commissioning

**Practice Exam:** 920-332 Exams

**Exam Number/Code:** 920-332

**Exam Name:** Mommunication Server 1000 Ris.5.0 Install & Commissioning

**Questions and Answers:** 96 Q&As

( [NCSS](#) )



"Mommunication Server 1000 Ris.5.0 Install & Commissioning", also known as 920-332 exam, is a Nortel certification. With the complete collection of exam questions, Just4Study has assembled to take you through 96 Q&As to your 920-332 exam preparation. In the 920-332 exam resources, you will cover every field and category in Nortel Certification helping to ready you for your successful Nortel Certification.

Exam : [920-332](#)

The exam questions cover the latest real test and with all the correct answer. we promise the Q&A for Nortel NCSS 920-332 (Mommunication Server 1000 Ris.5.0 Install & Commissioning) examination of original title complete coverage. 920-332 exam questions help you pass the exam.

#### **Just4Study 920-332 Feature:**

\* High quality - High quality and valued for the 920-332 Exam: 100% Guarantee to Pass Your 920-332 exam and get your NCSS certification.

\* Authoritative - Authoritative braindumps with complete details about 920-332 exam.

\* Cheaper - Our Just4Study products are cheaper than any other website. With our completed NCSS resources, you will minimize your **Nortel NCSS** cost and be ready to pass your 920-332 exam on Your First Try, 100% Money Back Guarantee included!

\* Free - Try free NCSS demo before you decide to buy it in <http://www.Just4Study.com>.

#### **Just4Study Guarantee:**

Just4Study provides the most competitive quality of all exams for the customers, we guarantee your success at the first attempt with only our Certification Question&Answers, if you do not pass the 920-332 exam at the first time, we will not only arrange FULL REFUND for you, but also provide you another exam of your claim, ABSOLUTELY FREE!

#### **Free 920-332 Demo Download**

Just4Study offers free demo for NCSS 920-332 exam (Mommunication Server 1000 Ris.5.0 Install & Commissioning). You can check out the interface, question quality and usability of our practice exams before you decide to buy it. We are the only one site can offer demo for almost all products.

The Questions & Answers cover the latest real test and with all the correct answer.we promise the Q&A for **Nortel NCSS 920-332** examination of original title complete coverage.920-332 Questions & Answers help you pass the exam. Otherwise,we will give you a full refund.

**VUE/Prometric Code: 920-332**

Exam Name: Mommunication Server 1000 Ris.5.0 Install & Commissioning( NCSS )

Questions and Answers: 96 Q&A

[Nortel 920-332](#) Test belongs to one of the NCSS certified test, if needs to obtain the NCSS certificate, you also need to participate in other related test, the details you may visit the [NCSS](#) certified topic, in there, you will see all related NCSS certified subject of examination.

Just4Study professional provide NCSS 920-332 the newest Q&A, completely covers 920-332 test original topic. With our complete NCSS resources, you will minimize your NCSS cost and be ready to pass your 920-332 tests on Your First Try, 100% Money Back Guarantee included!

### **Just4Study Help You Pass Any IT Exam**

[Just4Study.com](#) offers incredible career enhancing opportunities. We are a team of IT professionals that focus on providing our customers with the most up to date material for any IT certification exam. This material is so effective that we Guarantee you will pass the exam or your money back.

Exam : Nortel 920-332

Title : Mommunication Server 1000 Ris.5.0 Install &Commissioning3

1. You are deploying a Communication Server (CS) 1000E system with a CP-PM Call Server and the campus redundancy feature. It is mandatory that you configure the CP-PM Call Server side for the campus redundancy feature to operate properly. In which two locations is the Call Server side configured? (Choose two.)

- A. the BIOS menu
- B. the Installation menu
- C. the CLI using LD 97 Superloop commands
- D. the CLI using LD 117 CPU Location commands

Answer: AB

2. A customer has deployed a Communication Server (CS) 1000E network with a primary and a secondary site. In the event that the primary system fails, the customer requires each system backs up the IP telephones on the other system. The customer has been told this is possible and will require duplicate IP Phone Licenses on the second system. Which Redundant configuration is required?

- A. 1 + 1 configuration
- B. Campus Redundancy
- C. Controlled Load-sharing
- D. Survivable Media Gateway

Answer: C

3. A customer has installed the system components of a Communication Server (CS) 1000E system and has powered-up the system. Which visual indicator helps the customer differentiate whether a CP-PM card is running as a Call Server or a Signaling Server?

- A. Main Status LED
- B. FMD/HD Status LED
- C. Call Server Redundancy LED
- D. Embedded LAN (ELAN) Connection Status Link LED

Answer: C

4. A customer is installing a Media Gateway Controller (MGC) in a Communication Server (CS) 1000E system. The customer is connected to SDI 0 of the MGC to access the configuration menu. No IP information exists for the MGC. How does the customer get to the mgcsetup menu to configure the MGC?

- A. Type mgcsetup on the screen.
- B. No action required. The MGC will boot directly into the setup menu.
- C. The prompt Press any key to stop auto-boot and enter mgcsetup appears.
- D. Enter a shell command. <CTRL>O<CTRL>A<CTRL>M, provide OAM username and password to access OAM shell.

Answer: B

5. A customer has imported the node files from the Signaling Server to the Call Server in Element Manager. The customer sends the node configuration files to all IP Telephony components in the node using the Transfer/Status button. The Transfer/Status button on the Transfer/Status web page is yellow. What does this indicate?

- A. The transfer status of the node is in progress.
- B. The node configuration is transferred to the elements.
- C. The transfer status of the node elements is unavailable.
- D. An element within the node failed to transfer the BOOTP or CONFIG files.

Answer: C

6. When initially configuring the Data Networking and IP Telephony parameters for a Signaling Server on a Communication Server (CS) 1000E RIs. 5.0 system, which data is entered for a Follower Signaling Server?

- A. only the Telephony LAN (TLAN) parameters
- B. the hostname of the Leader Signaling Server
- C. only the Embedded LAN (ELAN) parameters
- D. the parameters for the IP Telephony node, ELAN, TLAN, and Call Server

Answer: B

7. A customer is planning system requirements for their Communication Server (CS) 1000E High Availability (HA) system. Based on system capabilities and system capacities with RIs. 5.0, which is the maximum number of Media Gateway 1000E systems supported?

- A. 5
- B. 20
- C. 30
- D. 50

Answer: D

8. A customer has successfully installed a Media Gateway Controller (MGC) in a Communication Server (CS) 1000E system. The MGC has registered with the Call Server. Which is displayed on the MGC LED display to confirm successful registration?

- A. The MGC display will read PASS.
- B. The MGC display will read LOAD.
- C. The MGC display will read Exxx ( E000).
- D. The MGC display will show Superloop and Shelf of MG 1000E (4 0).

Answer: D

9. A customer has deployed a Communication Server (CS) 1000E network with a primary and a secondary site. In the event the primary system fails, the customer requires the user database to be replicated from the primary site to the secondary site. Which Geographic Redundancy configuration meets the customers needs?

- A. CPP Redundancy
- B. Campus Redundancy
- C. Controlled Load-sharing
- D. Survivable Media Gateway

Answer: D

10. A customer has a Communication Server (CS) 1000E system with a cost optimized gateway controller and DSP daughterboards that support 96 VoIP voice gateway resources. The CS 1000E supports CeMux PSTN access cards in the Media Gateway 1000E, reducing the overall cost and complexity of the system. Based on these requirements, which is the recommended RIs. 5.0 hardware for the customer?

- A. CP-PM Call Server and MGC with High-Density DSP Daughterboard
- B. CP-PM Call Server, MGC without DSP Daughterboards, and MC 32S
- C. CP-PIV Call Server, MGC without DSP Daughterboards, and MC 32S

D. CP-PM Call Server and Media Gateway Controller (MGC) with Low-Density DSP Daughterboard

Answer: A

11. A customer is commissioning a Communication Server (CS) 1000E Rls. 5.0 system with Package 403 (Softswitch) and 402 (IPMG). The CP-PM Call Server software has been installed successfully, and now the customer is provisioning the Media Gateway Tone and Conference Loops for the Media Gateway Controller. Which switch overlay and prompt should the customer use to configure the Media Gateway TDS loop?

- A. LD 17, XCT
- B. LD 17, VXCT
- C. LD 97, SUPT
- D. LD 17, MGTDS

Answer: D

12. You are installing software for the first time on a new Communication Server (CS) 1000 Rls.5.0 Signal Server and receive the following message: The filesystems verification failed! Which action should you take next?

- A. Troubleshoot the hardware failure.
- B. Select the menu choice to abort the installation.
- C. Contact the next level of support to help diagnose the fault.
- D. Select the menu choice to partition and initialize the hard disk.

Answer: D

13. A customer has a Communication Server (CS) 1000E Rls. 5.0 system and is installing a stand-alone Signaling Server. Which role should you choose during the Signaling Server configuration?

- A. Leader
- B. Backup
- C. Follower
- D. Alternate

Answer: A

14. You have completed installing a Communication Server (CS) 1000E CP-PIV system. The system has been operating in normal conditions. One day, the lab temperature rises and causes the alarm/fan module temperature in the CP-PIV Call Server to exceed 60 degrees Celsius. What impact does this have on the system?

- A. A major alarm is triggered.
- B. The health of the active Call Server decreases.
- C. The Call Server Fan units switch into high-speed.
- D. The Call Server switches to the standby Call Server.

Answer: A

15. Which software installation must be completed before installing software on any Enterprise Media Gateway in a Communication Server (CS) 1000 Rls. 5.0 system?

- A. The Call Server software must be installed or upgraded.
- B. The IP telephone software must be available to all IP telephones.
- C. The ERS 8600 routing switches must be running the latest software revision.
- D. All Signaling Servers must be configured with the newest version of software.

Answer: A

16. A customer is implementing a Communication Server (CS) 1000 Rls.5.0 Communication Server 1000E High Availability (HA) system. The customer wants to know if there are any special package requirements beyond the HA Package needed for the system. Which two software packages are mandatory when deploying a CS 1000E HA system? (Choose two.)

- A. SBO - Branch Office Package 390
- B. SOFTSWITCH - Soft Switch Package 402
- C. IPMG - Media Gateway 1000E Package 403

D. SIP - SIP Gateway and Converged Desktop Package 406

Answer: BC

17. A customer has successfully installed and configured a Signaling Server in a Communication Server (CS) 1000E system. After configuration and reboot, the Follower Signaling Server sends out BOOTP requests and waits for a response. However, there is no BOOTP response. Which action should be taken?

- A. Reboot the Leader Signaling Server.
- B. Wait for a BOOTP response from the Leader Signaling Server.
- C. Configure the IP Telephony node for the Follower from Element Manager.
- D. Configure the IP Telephony node for the Follower from the Installation Tools menu.

Answer: C

18. A customer is planning to install a CP-PM Signaling Server into their Communication Server (CS) 1000 RIs. 5.0 Communication Server 1000E system. Which two hardware components or combinations does the customer need to identify in order to distinguish the CP-PM card as a Signaling Server? (Choose two.)

- A. Switch 5 set to Position 1
- B. Switch 5 set to Position 2
- C. two Compact Flash Drives (one RMD and one FMD)
- D. one Compact Flash Drive (RMD) and One Hard Drive (FMD)

Answer: BD

19. A customer has a Communication Server (CS) 1000E system with a cost optimized gateway controller and DSP daughterboards that support 160 VoIP voice gateway resources. The CS 1000E supports CeMux PSTN access cards in the Media Gateway 1000E, reducing the overall cost and complexity of the system. Based on these requirements, which is the recommended RIs. 0 hardware for the customer?

- A. CP-PM Call Server, MGC with High-Density Daughterboard, and MC 32S
- B. CP-PM Call Server and MGC with Low-Density and High-Density DSP Daughterboards
- C. CP-PM Call Server, MGC with Low and High-Density DSP Daughterboards, and MC 32S
- D. CP-PM Call Server and Media Gateway Controller (MGC) with Low-Density DSP Daughterboard

Answer: C

20. Upon opening the web browser to begin the login process into Element Manager on a Communication Server (CS) 1000E system, which two IP addresses can you enter into the address bar of the web browser? (Choose two.)

- A. the Call Server IP address
- B. the Signaling Server Node IP address
- C. the Terminal Proxy Server (TPS) IP address
- D. the Embedded LAN (ELAN) IP address of the Signaling Sever

Answer: BD

### [920-332 Braindumps](#)

#### **Related 920-332 Exams**

[920-803](#) Nortel technology standards and protocol for ip telephony solutions

[922-097](#) Comm.Server 1000 Upgrades to RIs.5.0 for Technicians

[920-250](#) nncss-passport 8600

[920-322](#) nncss succession 1000/1000m rls 3.0 db for technicians

[922-093](#) Communication Server 1000 RIs.5.0 System Admin & Mgmt

[922-096](#) Comm.Server 1000 RIs.5.0 Branch Office Install & Comm.

[922-095](#) Communication Server 1000E RIs.5.0 Install & Commisioning

[920-215](#) nncss-passport 7000/15000 exam

920-331 *Mommunication Server 1000 Ris.5.0 Database Administrator*

920-326 *nncds-symposium contact center poftfolio*

920-138 *NCSS Succession 1000/1000M Ris.3.0 Exam*

920-251 *nncss-alteon*

920-133 *NCSS Baystack Switching*

920-501 *nncss-optera metro 5000*

920-170 *symposium call center server 5.0 applicaiont developer*

920-249 *Nortel Application Switch Ris.23XConfig &Admin*

920-460 *ncse wireless lan*

920-330 *Mommunication Server 1000 Ris.5.0 IP Networking Design*

920-172 *NCSS-Nortel Communication Control Toolkit Ris.6.0*

920-245 *Ethernet Switching*

### **Other Nortel Exams**

920-440      920-120      920-262      922-020      920-556      920-192      920-191      920-807

920-571      920-532      920-270      922-021      922-055      920-805      920-197      922-097

920-258      920-133      920-121      920-160