

920-433 braindumps

Nortel Other Nortel Certification

920-433: Comm Svr 1000 Upgrades to Rls.5.0 for Techs, Linux & Apps

Practice Exam: 920-433 Exams

Exam Number/Code: 920-433

Exam Name: Comm Svr 1000 Upgrades to Rls.5.0 for Techs, Linux & Apps

Questions and Answers: 85 Q&As

([Other Nortel Certification](#))



"Comm Svr 1000 Upgrades to Rls.5.0 for Techs, Linux & Apps", also known as 920-433 exam, is a Nortel certification. With the complete collection of exam questions, Just4Study has assembled to take you through 85 Q&As to your 920-433 exam preparation. In the 920-433 exam resources, you will cover every field and category in Nortel Certification helping to ready you for your successful Nortel Certification.

Exam : [920-433](#)

The exam questions cover the latest real test and with all the correct answer. we promise the Q&A for Nortel Other Nortel Certification 920-433 (Comm Svr 1000 Upgrades to Rls.5.0 for Techs, Linux & Apps) examination of original title complete coverage. 920-433 exam questions help you pass the exam.

Just4Study 920-433 Feature:

* High quality - High quality and valued for the 920-433 Exam: 100% Guarantee to Pass Your 920-433 exam and get your Other Nortel Certification certification.

* Authoritative - Authoritative braindumps with complete details about 920-433 exam.

* Cheaper - Our Just4Study products are cheaper than any other website. With our completed Other Nortel Certification resources, you will minimize your **Nortel Other Nortel Certification** cost and be ready to pass your 920-433 exam on Your First Try, 100% Money Back Guarantee included!

* Free - Try free Other Nortel Certification demo before you decide to buy it in <http://www.Just4Study.com>.

Just4Study Guarantee:

Just4Study provides the most competitive quality of all exams for the customers, we guarantee your success at the first attempt with only our Certification Question&Answers, if you do not pass the 920-433 exam at the first time, we will not only arrange FULL REFUND for you, but also provide you another exam of your claim, ABSOLUTELY FREE!

Free 920-433 Demo Download

Just4Study offers free demo for Other Nortel Certification 920-433 exam (Comm Svr 1000 Upgrades to Rls.5.0 for Techs, Linux & Apps). You can check out the interface, question quality and usability of our practice exams before you decide to buy it. We are the only one site can offer demo for almost all products.

The Questions & Answers cover the latest real test and with all the correct answer.we promise the Q&A for **Nortel Other Nortel Certification 920-433** examination of original title complete coverage.920-433 Questions & Answers help you pass the exam. Otherwise,we will give you a full refund.

VUE/Prometric Code: 920-433

Exam Name: Comm Svr 1000 Upgrades to Rls.5.0 for Techs, Linux & Apps(Other Nortel Certification)

Questions and Answers: 85 Q&A

[Nortel 920-433](#) Test belongs to one of the Other Nortel Certification certified test, if needs to obtain the Other Nortel Certification certificate, you also need to participate in other related test, the details you may visit the [Other Nortel Certification](#) certified topic, in there, you will see all related Other Nortel Certification certified subject of examination. Just4Study professional provide Other Nortel Certification 920-433 the newest Q&A, completely covers 920-433 test original topic. With our complete Other Nortel Certification resources, you will minimize your Other Nortel Certification cost and be ready to pass your 920-433 tests on Your First Try, 100% Money Back Guarantee included!

Just4Study Help You Pass Any IT Exam

[Just4Study.com](#) offers incredible career enhancing opportunities. We are a team of IT professionals that focus on providing our customers with the most up to date material for any IT certification exam. This material is so effective that we Guarantee you will pass the exam or your money back.

Exam : Nortel 920-433

Title : Comm Svr 1000 Upgrades to Rls.5.0 for Techs. Linux & Apps

1. A customer has multiple Communication Server (CS) 1000Es. When calls are placed on hold, they want to provide the same music network-wide to their calls. Which configuration is needed for this support?

- A. Network Music is provided only to those calls that are transferred to the music source using Release Link Trunk over H.323.
- B. Music Trunks are installed only on the primary node, connecting to an analog TIE trunk using H.323/SIP virtual trunks. Only calls placed on hold at the primary node will receive this specific music source.
- C. Network Time Protocol (NTP) which is used to synchronize local clocks across the network to a single, accurate, third party NTP server, such as a radio clock.
- D. Music Trunks are installed on the remote nodes and connected back-to-back with an analog TIE trunk, which is auto-terminated to the primary DN of a Network Music Agent. When a music trunk is seized, the call is connected to the Audio Server through an H.323/SIP virtual trunk. A network music path is then established.

Answer: D

2. A customer is upgrading to a Communication Server 1000E Rls. 5.0 with a single Media Gateway 1000E chassis. In this configuration, which slot in the Media Gateway 1000E Chassis does not support the CP-PM Call Server?

- A. Slot 0
- B. Slot 1
- C. Slot 2
- D. Slot 3
- E. Slot 4

Answer: A

3. A customer is upgrading to Communication Server 1000E from Rls. 4.5 to Rls. 5.0 and is requesting Survivable Media Gateways in their network. Which packages support this functionality? (Choose two.)

- A. Package 409 for Global Plugins
- B. Package 410 for CP PM Server High Availability
- C. Package 404 for GRPRIM for the Primary System
- D. Package 405 for GRSEC for the Secondary System
- E. Package 499 for SSC Survivable Media Gateway

Answer: CD

4. A customer has upgraded to Communication Server 1000E Rls. 5.0 and is using the Management Tool NRSM on Linux. In conducting a search for Routing Entries, the engineer is looking for a specific number range. The engineer wants to secure all entries from the entire service domain and identify specific end points where they terminate. What is a more efficient procedure for searching for Routing Entries?

- A. Enter the specific DN type + the entire scope searching.

- B. Enter *56* (considered a wild card) + the entire scope searching.
- C. Enter #56# (considered a wild card) + the entire scope searching.
- D. Enter the specific service domain + the entire service domains to specific endpoints.

Answer: B

5. A customer is upgrading to Communication Server 1000E RIs. 5.0. The customer wants to take advantage of Secure Media Exchange (SRTP) so voice conversations are secure. What needs to occur for Media Security to be provided?

- A. IP Phones Phase 1 must be using the DSPs located on the MGC and MC32S cards only.
- B. IP Phones Phase 2 must be using the DSPs located on the Voice Gateway Media Cards only.
- C. IP Phones Phase 0 must be using the DSPs located on the MGC and MC32S cards only.
- D. IP Phones Phase 2 must be using the DSPs located on the MGC and MC32S cards only

Answer: D

6. A customer is upgrading to a Communication Server 1000E RIs. 5.0. Which hardware components also provide DSP services? (Choose two.)

- A. 32-port DSP Daughterboard
- B. 96-port DSP Daughterboard
- C. 128-port DSP Daughterboard
- D. Media Gateway Controller card (MC32B)

Answer: AB

7. A customer is upgrading from Meridian 1 Option 11C RIs. 24 to a Communication Server 1000E RIs. 5.0 Standard Availability with a single Media Gateway 1000E chassis and has decided to install a new CP-PM Call Server card. Which step(s) are required to migrate a Small System database to the CP-PM?

- A. Complete an inventory of the Small System using LD 117 and then migrate using LD 10 and LD 11.
- B. Backup the Small System database using LD 43 EDD and then archive the database using LD 143.
- C. Configure MGCONF and MGTDS separately and map them to a specific CP-PM CS prior to migration.
- D. Use the `issp` command in LD 22 to determine MGC Loadware PEPS and then use the `lwinst` command to activate the MGC Loadware patch.

Answer: B

8. A customer is upgrading from Communication Server 1000E RIs. 5.0 Standard Availability to Communication Server 1000E RIs. 5.0 High Availability. In addition to a Media Gateway 1000E, what configuration must be in place for this to occur?

- A. A CP-PM and an MGC
- B. A CP-PM CS, an MGC, and package 410 High Availability
- C. A CP-PM CS, CP-PM SS, an MGC, and package 405 GRSEC
- D. A CP-PM CS with either a CP-PM SS, ISP 1100 or COTS VxWorks SS, and an MGC, and package 410 High Availability

Answer: D

9. CP-PM, IBM X306m and HP DL320-G4 are all platforms which support the Signaling Server applications on Release 5.0. Which server comes with the software installed?

- A. CP-PM
- B. IBM X306m
- C. HP DL320-G4
- D. None of the servers

Answer: A

10. A customer is upgrading to Communication Server (CS) 1000E RIs. 5.0. The customer wants to utilize TLS for SIP traffic security in their network. What security does TLS provide?

- A. TLS provides audio encryption between SIP clients only.

- B. TLS provides audio encryption between Unistim clients only.
- C. TLS provides signaling encryption between all SIP endpoints.
- D. TLS provides signaling encryption between all system clients.

Answer: C

11. A customer is upgrading from a Meridian Option 11C to Communication Server 1000E RIs. 5.0 with an IP Media Gateway. With this configuration, they are using both the 32-port and 96-port DSPs on the MGC. If they need more DSPs, what is the available configuration option?

- A. An MC32S can be added.
- B. Change out the Low Density DSP to a second High Density DSP.
- C. A second IPMG would need to be installed to provide the additional DSPs.
- D. The entire system would be to be re-engineered to ensure timeslots are available for MGCONF and MGTDS resources.

Answer: A

12. A customer has upgraded from a Communication Server (CS) 1000S to a CS 1000E Standard Availability (SA). Due to their projected company and network growth, they are contemplating upgrading to a CS 1000E High Availability (HA) system. Which component(s) differentiate a HA system from a SA system?

- A. a second CP-PM
- B. enabling the HA software package
- C. a second CP-PM and a CP-PM Call Server
- D. a second CP-PM and enabling the HA software package

Answer: D

13. A customer is upgrading from a Communication Server 1000S to Communication Server 1000E RIs. 5.0 and requires a High Availability configuration. Which package must be in place for this to occur?

- A. Package 329 for ESA
- B. Package 410 for CP-PM Servers
- C. Package 404 for GRPRIM for Primary System
- D. Package 405 for GRSEC for Secondary System

Answer: B

14. A customer is upgrading an existing Media Gateway 1000T RIs. 4.5 with an expansion to a stand alone Communication Server (CS) 1000E RIs. 5.0 with two IP Media Gateways and a Signaling Server that is a Nortel ISP 1100. After the installation, which should you do to verify that there is sufficient memory to support the upgrade to RIs. 5.0?

- A. View the attributes of the Signaling Server using Element Manager.
- B. Remove the cover from the ISP 1100 and look at the label(s) on the DIMM board(s).
- C. Boot the Signaling Server and monitor the startup messages for configured memory.
- D. Follow the procedure to verify successful memory upgrade and look for the message 1 GByte OK, since 1 GB of memory is required in the ISP 1100.

Answer: D

15. A customer is upgrading a Communication Server 1000S to a Communication Server 1000E RIs. 5.0. Which hardware component replaces the Media Gateway 1000S controller card?

- A. DSP Daughterboard
- B. Media Card 32 Port Security
- C. No hardware change required.
- D. Media Gateway Controller card
- E. Call Processor Pentium Mobile

Answer: D

16. A customer is upgrading to Communication Server 1000E RIs. 5.0 and needs additional temporary IP User

Licenses for controlled load sharing between two systems. Which statement is true regarding the licenses to be ordered and the use of additional IP User Licenses?

- A. No additional licenses need to be ordered. If the customer runs out of IP User Licenses for the 1150E, they can use the Basic IP User Licenses.
- B. Basic IP User Licenses must be ordered. Regular IP Licenses will be used if the temporary license count is exceeded.
- C. Regular IP User Licenses must be ordered. Basic IP User Licenses will be used if the temporary license count is exceeded.
- D. Temporary User Licenses should be ordered. Basic IP or Regular IP User Licenses will be used if the temporary license count is exceeded.

Answer: D

17. A customer is upgrading to a Communication Server 1000E RIs. 5.0. To take advantage of features supported by the Enterprise Common Manager (ECM) framework, which systems can be deployed as the ECM? (Choose two.)

- A. VxWorks Operating System and ISP 1100
- B. Linux Operating System and IBM x306m
- C. Linux Operating System and HP DL 320
- D. VxWorks Operating System and HP DL 320
- E. VxWorks Operating System and IBM x306m

Answer: BC

18. A customer is upgrading to Communication Server 1000E RIs. 5.0. During their database configuration, they need to ensure that the Emergency Services for Client Mobility feature is supported, but they are uncertain whether their upgrade supports this application. What prompt(s) should be enabled, and what configuration is needed to ensure this support?

- A. ESA must be disabled. Emergency Response Location (ERL), Emergency Caller Location (ECL) and internal Location Information Service (Package 336) must be programmed.
- B. ESA Package 329 must be enabled and programmed, allowing the Emergency Response Location (ERL) and Emergency Caller Location (ECL) and internal Location Information Service (Package 336) to be used.
- C. New System Type 4021 must be activated before the Emergency Response Location (ERL) and Emergency Caller Location (ECL) appear in Web Station.
- D. The addition of HA Package 410 must be activated before the Emergency Response Location (ERL) and Emergency Caller Location (ECL) appear in Web Station.

Answer: B

19. A customer is upgrading to Communication Server 1000E RIs. 5.0. With this configuration, they will be using all of the Management Features; however, they are currently at Optivity Telephony Manager (OTM) RIs. What is the upgrade path for the most current Telephony Manager (TM) offering, and what will occur to the database during the upgrade?

- A. Only an upgrade from OTM RIs. 2.2 to TM RIs. 3.0 is supported, and the database is automatically migrated during the upgrade.
- B. A direct upgrade from OTM RIs. 2.2 to TM RIs. 3.1 is supported, and the database is automatically migrated during the upgrade.
- C. A direct upgrade from OTM RIs. 2.2 to TM RIs. 3.1 is supported, with the database having to manually be migrated during the upgrade.
- D. Only an upgrade from TM RIs. 3.0 to TM RIs. 3.1 is supported, with the database having to be manually migrated during the upgrade.

Answer: B

20. A customer is upgrading from a Meridian Option 11C to a Communication Server (CS) 1000E RIs. 5.0 Standard Availability. What happens to the Terminal Numbers (TNs) during the upgrade?

- A. The Small System (Card-Unit) TNs are retained.
- B. The TNs are automatically converted to the Large System format (Loop - Shelf - Card - Unit) for all assigned TNs.

C. The TNs are manually changed to the Large System format (Loop - Shelf - Card - Unit) by re-programming all devices assigned TNs.

D. The TNs for only the IP Phones are automatically converted to the Large System format (Loop - Shelf - Card - Unit). All other devices assigned TN must be manually re-programmed.

Answer: B

[920-433 Braindumps](#)

Related 920-433 Exams

922-109	<i>Communications Server 1000 RIs.6.0 BARS/NARS</i>
922-111	<i>Communication Server 1000 to RIs.6.0 Upgrades for Technicia</i>
922-081	<i>CallPilot RIs.5.0 Networking</i>
920-457	<i>CallPilot RIs.4.0 Unified Messaging Exam</i>
922-071	<i>BCM50 RIs.3.0 & BCM200/400 RIs.4.0 Config & Maintenance</i>
920-569	<i>nncds-optera metro solutions</i>
920-502	<i>nncss-optera metro 3000</i>
922-104	<i>Communication Server 1000 RIs.6.0 Upgrades for Engineers</i>
920-193	<i>ncss-business communications manager 50(bcm50)rls.1.0</i>
920-110	<i>NNCSS SL-100 Maintenance Certification Exam</i>
920-338	<i>BCM50 RIs.3.0 BCM200/400 RIs 4.0&BCM450 RIs. 1.0 Instal Con</i>
920-806	<i>Nortel Advanced Data Networking Technology</i>
920-220	<i>Nortel Converged Campus ERS Solution</i>
920-805	<i>Nortel Data Networking Technology</i>
922-030	<i>Carrier VoIP Engineering Fundamentals</i>
922-094	<i>Communication Server 1000 RIs.5.0 Dialing Plan Design & IP</i>
920-327	<i>MCS 5100 RIs.4.0 Commissioning & Administraion</i>
920-162	<i>callpilot 4.0 installation and maintenance exam</i>
920-123	<i>NCSS-BayStack/BPS Switching Exam</i>
920-432	<i>Communication Server 1000 RIs.5.0-BCMRIs.4.0 Multi-site</i>

Other Nortel Exams

922-058	920-242	920-110	922-094	920-334	920-463	922-096	920-271
920-556	920-328	920-259	920-544	922-071	920-233	922-109	922-080
920-245	922-100	920-220	920-191				