

E20-850 braindumps

EMC EMC Certification

E20-850: CLARiiON Implementation Engineer Expert

Practice Exam: E20-850 Exams

Exam Number/Code: E20-850

Exam Name: CLARiiON Implementation Engineer Expert

Questions and Answers: 376 Q&As

([EMC Certification](#))



"CLARiiON Implementation Engineer Expert", also known as E20-850 exam, is a EMC certification. With the complete collection of exam questions, Just4Study has assembled to take you through 376 Q&As to your E20-850 exam preparation. In the E20-850 exam resources, you will cover every field and category in EMC Certification helping to ready you for your successful EMC Certification.

Exam : [E20-850](#)

The exam questions cover the latest real test and with all the correct answer. we promise the Q&A for EMC EMC Certification E20-850 (CLARiiON Implementation Engineer Expert) examination of original title complete coverage. E20-850 exam questions help you pass the exam.

Just4Study E20-850 Feature:

* High quality - High quality and valued for the E20-850 Exam: 100% Guarantee to Pass Your E20-850 exam and get your EMC Certification certification.

* Authoritative - Authoritative braindumps with complete details about E20-850 exam.

* Cheaper - Our Just4Study products are cheaper than any other website. With our completed EMC Certification resources, you will minimize your **EMC EMC Certification** cost and be ready to pass your E20-850 exam on Your First Try, 100% Money Back Guarantee included!

* Free - Try free EMC Certification demo before you decide to buy it in <http://www.Just4Study.com>.

Just4Study Guarantee:

Just4Study provides the most competitive quality of all exams for the customers, we guarantee your success at the first attempt with only our Certification Question&Answers, if you do not pass the E20-850 exam at the first time, we will not only arrange FULL REFUND for you, but also provide you another exam of your claim, ABSOLUTELY FREE!

Free E20-850 Demo Download

Just4Study offers free demo for EMC Certification E20-850 exam (CLARiiON Implementation Engineer Expert). You can check out the interface, question quality and usability of our practice exams before you decide to buy it. We are the only one site can offer demo for almost all products.

The Questions & Answers cover the latest real test and with all the correct answer.we promise the Q&A for **EMC EMC Certification E20-850** examination of original title complete coverage.E20-850 Questions & Answers help you pass the exam. Otherwise,we will give you a full refund.

VUE/Prometric Code: E20-850

Exam Name: CLARiiON Implementation Engineer Expert(EMC Certification)

Questions and Answers: 376 Q&A

[EMC E20-850](#) Test belongs to one of the EMC Certification certified test, if needs to obtain the EMC Certification certificate, you also need to participate in other related test, the details you may visit the [EMC Certification](#) certified topic, in there, you will see all related EMC Certification certified subject of examination.

Just4Study professional provide EMC Certification E20-850 the newest Q&A, completely covers E20-850 test original topic. With our complete EMC Certification resources, you will minimize your EMC Certification cost and be ready to pass your E20-850 tests on Your First Try, 100% Money Back Guarantee included!

Just4Study Help You Pass Any IT Exam

[Just4Study.com](#) offers incredible career enhancing opportunities. We are a team of IT professionals that focus on providing our customers with the most up to date material for any IT certification exam. This material is so effective that we Guarantee you will pass the exam or your money back.

Exam : EMC E20-850

Title : CLARiiON Implementation Engineer Expert

1. Which software in addition to Navisphere Management Server must be installed on a laptop to allow viewing of Analyzer .nar files when there is no network connectivity?

- A. Navisphere Analyzer Provider
- B. Navisphere Host Agent
- C. Navisphere Manager
- D. Navisphere Off-Array UIs

Answer: D

2. A customer engineer changed default LUN ownership of LUN5 from SPA to SPB in an attempt to balance SP utilization.

With the least amount of host impact, what is the next step?

- A. Reboot the attached host
- B. Run:
powermt check reconfig
powermt restore class=clariion
- C. Use CLI to trespass the LUN
- D. Use Navisphere Manager to trespass the LUN

Answer: B

3. A customer is using Replication Manager to back up its Exchange 2007 environment.

To improve performance for backup and maintenance tasks, what allocation unit size should the Exchange Database and Log volumes be formatted to?

- A. 32K
- B. 4096K
- C. 64K
- D. 8192K

Answer: C

4. SES Analysis Inc. has two CX500s separated by a distance of 8 km. The company wants to implement several asynchronous mirrors. The admin created three asynchronous mirrors, and received an error message when trying to create the fourth.

The array has 31 LUNs using SnapView snapshots, and the total number of snapshots is 47. SES is also using Incremental SAN Copy on 16 other source LUNs. Each Incremental SAN Copy session has two destinations. Another 16 source LUNs have two clones each.

Why is SES seeing the error messages?

- A. Number of Incremental SAN Copy images exceeds the maximum allowed on a CX500

- B. Number of mirror and clone images exceeds the number allowed on a CX500
- C. Number of snapshots exceeds the maximum allowed on a CX500
- D. Required number of LUNs in the Reserved LUN Pool exceeds the allowed maximum on a CX500

Answer: D

5. LUN 300 is a Clone of LUN 100, a 512 GB LUN. Both LUNs are on 4+1 RAID 5 RAID Groups, and were bound with default values.

The Clone is currently synchronizing at the medium synchronization rate. LUN 100 is performing random 4 kB writes at a rate of 60 IOPs.

Which I/O sizes will be seen on the clone in the Navisphere Analyzer > I/O Size Distribution Summary view?

- A. 128 kB and 256 kB
- B. 4 kB and 128 kB
- C. 4 kB and 64 kB
- D. 64 kB and 128 kB

Answer: B

6. MMC uses MirrorView/S between two data centers. The company currently uses the write intent log (WIL) feature on both arrays. The production workload was transferred to the remote data center after a disaster. When MMC failed back to the production data center, the company experienced full resynchronizations of all its MirrorView/S LUNs.

Why did this situation occur?

- A. WIL from the primary site is irrelevant after the MirrorView/S secondary images have been promoted.
- B. WIL is stored on the SP cache and it was lost during the outage.
- C. WIL was lost on the production data center during the outage and a full re-synchronization of all the LUNs was required.
- D. WIL was never transferred after the outage.

Answer: A

7. Company XYZ has MirrorView/A deployed with consistency groups. A system administrator expands a LUN in the consistency group to a metaLUN.

Using the least amount of administrative effort, what actions need to be taken to continue the consistency group relationship?

- A. Destroy consistency group, re-create consistency group
- B. Destroy mirror, re-create mirror
- C. Leave consistency group alone
- D. Remove mirror from consistency group, destroy mirror, re-create mirror, add mirror to consistency group

Answer: D

8. What type of service account does Replication Manager require to back up Microsoft Exchange stores?

- A. Domain account with Exchange rights and Local Server Admin rights
- B. Domain account with Exchange rights
- C. Domain account
- D. Local Admin account on the Exchange server

Answer: A

9. An Exchange 2007 user realizes that it accidentally deleted a business-critical mail item from its mailbox just over two (2) weeks ago. It has been replicating this environment utilizing SnapView clones for several months.

This is the first time mail item recovery has been required since implementing SnapView clones.

Which steps must the administrator take in order to recover the deleted mail item using the least amount of administrative effort?

- A. Boot into a parallel Active Directory and install Exchange with the identical parameters as production. Mount the SnapView clone and use ExMerge to extract the mail item
- B. Instruct the user to recover the mail item from deleted item retention
- C. Mount the SnapView clone to a recovery storage group and restore the mail item for the user

D. Restore the mailbox database from streaming backup, and mount it to a recovery storage group, then restore the mail item

Answer: C

10. A customer uses a 300 GB LUN for its application. It would like to take a snapshot to use for testing purposes by the backup server. It's expected that the backup server testing will perform enough writes to change all the data.

What is the size recommended for the Reserved LUN Pool to handle the snapshot load?

A. 300 GB

B. 400 GB

C. 500 GB

D. 600 GB

Answer: D

11. A company needs to create clone LUNs on a CLARiiON array. These LUNs will be used by Replication Manager to back up the SQL Server MDF and LDF LUNs.

Where must the clone LUNs be created to have the least impact on the SQL Server?

A. In the same RAID group as the SQL MDF files

B. In the same RAID group as the SQL LDF files

C. In their own RAID group

D. In a RAID group shared with another application

Answer: C

12. You are planning for a migration of your SQL Server production instance from DAS to SAN. EMC has requested the number of IOPS required for planning purposes.

Which performance counter will provide the requested information?

A. PhysicalDiskDisk Transfers/sec of the database and transaction log LUNs

B. LogicalDiskDisk Transfers/sec of the database and transaction log LUNs

C. PhysicalDiskAvg. Disk Bytes/Transfer of the database and transaction log LUNs

D. LogicalDiskAvg. Disk Bytes/Transfer of the database and transaction log LUNs

Answer: A

13. A customer uses a SnapView snapshot for local data replication of a 100 GB LUN. Recently the customer noticed that the snapshot session consumes 90 GB of the Reserved LUN Pool.

Which best practice addresses the situation?

A. Additional LUNs should be added to the Reserved LUN Pool.

B. Size of the existing LUNs in the Reserved LUN Pool should be increased.

C. SnapView chunk size should be changed to optimize capacity usage.

D. SnapView clone should be used instead of a snapshot.

Answer: D

14. When a storage administrator attempts to start all SAN Copy sessions in a script to their CX600, only the SPA sessions start.

What is the issue with the script?

A. Script does not have the correct password for SPB.

B. Script is not using the correct session names.

C. Script issues all commands against SPA.

D. Script issues all commands against SPB.

Answer: C

15. What is the tool for setting registry values for an Emulex driver in a Windows 2K3 server environment?

A. lputilnt

B. regedit

C. regedit32

D. regedt

Answer: A

16. A customer needs to collect performance data from a CX3-80 for trend analysis. The array was recently upgraded from FLARE 22 to FLARE 24. The new file has a .naz extension, while the files prior to the upgrade have .nar extensions. The customer uses the updated management workstation to view the performance data offline but is unable to open the new files.

Why?

A. There is an incorrect version of the Off-Array Manager.

B. Log file is encrypted

C. Navisphere Analyzer Enabler is not installed.

D. Statistics logging has not been started

Answer: B

17. What would make MirrorView/S unsuitable as a remote replication solution for an SQL implementation?

A. Distance of 1.5 km between primary and secondary sites

B. A dark fiber connection between sites

C. 20 ms average latency with mirroring for read/write operations on the database

D. 60 ms average latency with mirroring for write operations on the transaction logs

Answer: D

18. HHH Corp. is in the process of an Incremental SAN Copy migration between CLARiiON arrays. During the migration, the source LUN fails and causes the reserved snapshot session to stop.

After the source LUN is fixed, what must be done to start the session?

A. Modify the session to a full session and back to an incremental

B. No user action; session will start automatically

C. Session must be destroyed and re-created

D. Start the session manually

Answer: A

19. A customer added a second CLARiiON array to their SQL Server configuration. The array is present in Navisphere.

A discovery in Replication Manager fails to find any LUNs even though the LUNs are present in the assigned CLARiiON storage group.

What should be done to fix the problem?

A. Add the CLARiiON array name in the host configuration file.

B. Add the correct host privileges to the SP agent file on the array.

C. Check the clarcnfg file on the host and add SP IP addresses and array serial numbers.

D. Check the clarcnfg file on the array and add the name of the SPs and array serial number to it.

Answer: C

20. Which SAN Copy command line utility is used to flush Windows host buffers?

A. Admhost

B. Admsnap

C. NaviCLI

D. NaviSecCLI

Answer: A

[E20-850 Braindumps](#)

Related E20-850 Exams

[E20-001](#) Storage Technology Foundations (Information Storage and Mgmt)

[E22-211](#) Mainframe Remote Replication Exam

E20-611 CLARiiON Installation and Troubleshooting Specialist

E20-120 EMC Content Management Foundation Exam(CMF)

E20-361 Network Attached Storage (NAS) Implementation Exam

E20-616 Symmetrix Installation and Troubleshooting Specialist

E20-011 Storage Networking Design and Management

E20-351 Storage Attached Network (SAN) Specialist Exam

E22-280 Avamar Backup and Data Deduplication Exam

E20-501 Commercial Storage & Info Infrastructure Exam for Tech Archs

E20-455 Content Management Web Application Programming Exam

E22-201 Mainframe Local Replication Exam

E20-590 Backup and Recovery Specialist Exam

E20-485 Content Management Application Architecture Exam

e20-661 Networked Storage-NAS Installation and Troubleshooting Exam

E20-465 Content Management System Administration

e20-617 DMX Migration

e20-845 Business Continuity Expert Exam for Implementation Engineers

E20-475 Content Management Systems Architecture

e20-537 networked storage-ns exam for storage administrators

Other EMC Exams

| | | | | | | | |
|----------------|----------------|----------------|----------------|----------------|----------------|----------------|----------------|
| <u>E20-405</u> | <u>e22-141</u> | <u>e20-855</u> | <u>e20-822</u> | <u>e20-870</u> | <u>e20-330</u> | <u>e20-825</u> | <u>E22-181</u> |
| <u>E20-840</u> | <u>e20-060</u> | <u>e22-128</u> | <u>e20-322</u> | <u>E20-500</u> | <u>E20-593</u> | <u>E20-322</u> | <u>e20-050</u> |
| <u>e20-535</u> | <u>E22-310</u> | <u>E20-370</u> | <u>e20-090</u> | | | | |